

## Demos checklist

- Bucking    Compression/Tension
  - Step-cut
  - V cut
  - Wedging
  - Offset left of kickback path
- Limbing    Sweep
  - Lever
  - Big branches
- Bolt cuts
- Sight lines
- SCOWL brush+cut
- Spring poles
- Boring cuts
- Wedging
- Hangers    Turning
  - Step-cut
  - Knee joint
- Leaners    Heavy        Small+Big
  - Against the lean
- Sit-backs